UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU
U UNCLASSIFIED U
UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU

ADMINISTRATIVE MESSAGE

ROUTINE

R 061539Z JAN 88 ZYB

FM COMNAVAIRSYSCOM WASHINGTON DC

TO AIG ONE ONE ONE NINE EIGHT

UNCLAS //N13670//

SUBJ: SE-4 SUPPORT EQUIPMENT BULLETIN 582 TO CODE 63 MOBILE FACILITY 60HZ AND 400HZ POWER INPUT/TRANSFER CONNECTOR PIN INSPECTION OF

A. NAVAIR AG-360MF-11N-000
B. SUPPORT EQUIPMENT CHANGE NO. 3362 ISSUE DATE 30 SEP 86

1. COG CODE: AIR-41712A, J. PFIZENMAYER AV 222-2226

2. CATEGORY: URGENT

3. DOCUMENTATION AFFECTED: N/A

4. PURPOSE: TO REDUCE POTENTIAL HAZARD OF PIN UNSEATING DURING POWER CABLE HOOK-UP/REMOVAL OPERATION

5. APPLICATION: (1) ALL NAVAIR MOBILE FACILITIES WITH SEC-3362 INCORPORATED

SERIAL NUMBER	SERIAL NUMBER
59-00566 THRU 59-00597	
59-00665 THRU 59-00867	GFS-0001 THRU GFS-0021
59-00982 THRU 59-01133	GRT-001 THRU GRT-260
59-01253 THRU 59-01311	GTG-001 THRU GTG-102

DLVR:PROJMGR FLT HOSP WASHINGTON DC(2)...ACT

41712A(2)...ORIG FOR COMNAVAIRSYSCOM WASH(6) 00647/15/2044
4171S(1) 417S(1) 07E1(1) FC(1)

09B362(1)...ACT FOR COMNAVSEASYSCOM WASH(2) 13670/ 1/2315
93(1)

PMW180(2)...ACT FOR COMSPAWARSYSCOM WASH(5) 00647/ 2/0134
SDO(1) 003(1) 18-511(1)

RTD:000-000/COPIES:0015

295880/008 1 OF 2 MATA0810 008/07:06Z 061539Z JAN 88
OON:VDTI00045 COMNAVAIRSYSCO

UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU
U UNCLASSIFIED U
UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU

59-01253 THRU 59-01388 JKS-001 THRU JKS-102
EJE-001 THRU EJE-0339 JMJ-001 THRU JMJ-320
(2) ALL KZT, MWK, PAQ PBT, PPC AND QHR SERIES MF'S

6. COMPLIANCE: INTERMEDIATE MAINTENANCE LEVEL ACTIVITIES NLT 90 DAYS AFTER RECEIPT OF SEB

7. MAN-HOURS REQUIRED

	NO OF MEN	SKILL	MAN-HOURS
A. BASIC EQUPMENT	1	AMS	.5
	1	AE	.5

8. SUPPLY DATA: REPLACEMENT-THROUGH NORMAL SUPPLY CHANNELS

9. RE-IDENTIFICATION: N/A
10. DETAILED INSTRUCTIONS:
A. 9E-ENERGIZE ALL ELECTRICAL POWER TO MOBILE FACILITY
B. REMOVE ALL ELECTRICAL POWER CABLES FROM MOBILE FACILITY
C. FEMALE CONTACTS: INSERT A SINGLE MALE PIN OR A WOODEN DOWEL INTO EACH CONTACT AND PUSH OR LIGHTLY TAP ON PIN. FEMALE CONTACT SHOULD REMAIN FIRMLY IN PLACE.
D. MALE PINS: INSERT A SINGLE FEMALE CONTACT OVER EACH PIN AND PUSH OR TAP LIGHTLY ON CONTACT. MALE PIN SHOULD REMAIN FIRMLY IN PLACE.
E. IF EITHER MALE PINS OR FEMALE CONTACT DO NOT REMAIN FIRMLY SEATE9:
(1) REMOVE THE POWER PANEL COVER/TRANSFER PANEL COVER INSIDE THE MOBILE FACILITY.
(2) PUSH THE IMPROPERLY SEATED PIN/CONTACT BACK INTO LOCKED POSITION USING A PIN INSERTION TOOL.
(3) REPEAT STEPS 'C' OR 'D' AS APPROPRIATE.
F. ALL MALE NEUTRAL PINS SHOULD PROTRUDE SLIGHTLY BEYOND THE PHASE PINS.
11. WEIGHT AND BALANCE: N/A
12. RECORDS AFFECTED: MOBILE FACILITY LOGBOOK AND INVENTORY RECORD ENTRY
13. VERIFIED BY: N/A
14. RECISSION: 30 JUNE 88
15. RELATED INSTRUCTIONS: N/A

BT