

ACTION ITEM NO: 1-100

DATE SUBMITTED: 19 JUL 98

SUBMITTED BY: MALS-31

PROBLEM:

Recess the 115 VAC 60 Hz Power Receptacle.

DISCUSSION:

The 115 VAC 60 Hz power receptacle located next to the power monitor panel and adjacent to the Environmental Control Unit (ECU) is prone to damage when sliding the ECU in and out of the Mobile Facility (MF) The placement of the receptacle needs to be moved or recessed to prevent unnecessary damage.

RECOMMENDATION:

It is requested that the 115 VAC 60 Hz power receptacle be recessed in its current location or moved to allow the ease of sliding the ECU in and out of the MF. This engineering change, which could be performed at the local W/C 990, would prevent unnecessary damage to the outlet.

ACTION AGENCY:

NAWCADLKE CODE 4825

Open. NAWCADLKE Code 4825 to provide analysis.

COMPLETION DATE:

16 NOV 98

STATUS: 02 DEC 98

Open. NAWCADLKE Code 482500B562-3 currently in process of incorporating recessed outlet in current contract. After details are finalized, information will be provided to the fleet for incorporation of recessed outlet on an as needed/desired basis.

COMPLETION DATE:

15 FEB 99

STATUS: 28 APR 99

Open. No current status to date.

STATUS: 15 JUL 99

Closed. NAWCADLKE Code 3.1.4.4 to issue IRAC via next publication of MF Newsletter. The present MF Shelter Production Contract has incorporated a change for the recessed 115 VAC 60 Hz power receptacle.