

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 5-62

DATE SUBMITTED: 04/30/2010

SUBMITTED BY: GYSGT GIPSON

PROBLEM: 200KW LOAD BANK, P/N LPH200D35584 AVTRON Publication.
Avtron publication does not provide sufficient troubleshooting procedures or parts labeling. The pub provides parts with part numbers, but does not give parts description or function. It also does not provide an Illustrated Parts Breakdown (IPB) to reference part location, only a wiring diagram.

RECOMMENDATION: Recommend Avtron update the manual to provide better troubleshooting procedures, include a part description/function section, and incorporate an Illustrated Parts Breakdown (IPB) to reference part location. This should provide the technician a better understanding of Load Bank theory of operation and parts location to sufficiently troubleshoot and correct any problems.

STATUS: Accepted

ACTION AGENCY: Lakehurst