

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 1-112

DATE SUBMITTED: 20 May 2004

SUBMITTED BY: MALS-36, W/C 990

PROBLEM: On many INU's the window AC cover folds upward for storage purposes. Over time, even a slight nudge can misshape it; and even after re-forming, a tight seal isn't guaranteed. Water leaks are inevitable causing interior damage and mold.

RECOMMENDATION: On new MF's, incorporate a "plug" styled cover similar to the ECU or INU plug. It should be just as thick, have a gasket, and seal with dog-legs.

STATUS: 01 JUN 04

ACTION AGENCY: TBD

STATUS: 17 JUN 04

NEW ACTION CO-AGENCY:

NADEPNI/PWC NORFOLK CONFIG SITE  
USMC LIAISONS

Open. NADEPNI Code 97601 and PWC NORFOLK Code 505 to investigate and provide findings on gasket materials.

COMPLETION DATE:

TBD