

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO: 1-117

DATE SUBMITTED: 04/18/07

SUBMITTED BY: AS1(AW) Ken White, Expeditionary Logistics Unit ONE

PROBLEM: The retrofit of the CASS HP MMF (KA-10) SEC 5698, Side Opening Mobile Facility w/CASS RF HPDTS, Modification of WUC 33AJ0, did not include the updated engineering drawings in the Technical Directive. All MF KA-10 configurations fleet-wide should include the modified drawings in the LIR because the only accurate sources of part numbers pertinent to the SEC are located in the engineering drawings.

RECOMMENDATION: Request modified engineering drawings for MF KA-10 configurations get included as Amendment 1 to SEC 5698 and deliver to the fleet.

ACTION AGENCY: MF program Engineering

STATUS: 5/23/2007 Accepted and will be addressed by North Island Engineering

06/13/07 - Configuration code KA-10, CASS RF WITH HPDTS TEST STATION MF B, drawing No. MFKA100101, currently revision L is in question here. SEC 5698, SIDE OPENING MOBILE FACILITY W/ CASS RF HPDTS MODIFICATION OF, is to retrofit all configurations KA-10. Drawing No. MFKA100161, revision D, is the modification drawing used in the SEC and was included as an enclosure to the SEC. Another copy of this drawing was sent with the kit in order to update the LIR and instructions were included to do so.

We can not provide ELU-1 or any MALS with revised drawing No. MFKA100101 rev L since that particular MF was configured with a different revision KA-10. To update the LIR, only the modification drawing must be included in the LIR after they completed the TD.

Pete Vicencio

07/26/07 – ACTION COMPLETE.