

ACTION ITEM NO: 2-146

DATE SUBMITTED: 19 JUL 98

SUBMITTED BY: MALS-31

PROBLEM:

Aviation Breathing Oxygen Analyzer Mobile Facility (MF) TBA requirement.

DISCUSSION:

Currently, the Table of Basic Allowance (TBA) does not address a MF requirement for an Aviation Breathing Oxygen Analyzer MF which would be required to deploy with the host MALS in the event of a contingency. The unit requires an environmentally controlled shelter. MALS-31 has two such Analyzers, both items are to be identified under the CCSP contingency package.

RECOMMENDATION:

It is requested that two (2) CL-02 configurations be added to MALS TBA to meet the maintenance requirements. This present configuration within the MF inventory has enough work surface area to allow the placement of one Analyzer and adequate tools and associated support equipment storage.

**STATUS: 29 JUL 98**

ACTION AGENCY:

NADEP NORTH ISLAND (Code 48701)

Open. NADEP North Island Code 48701 to provide analysis.

COMPLETION DATE:

16 NOV 98

**STATUS: 30 SEP 98**

Closed. Mobile Facilities Engineering, Code 48701, has reviewed action item and to comply, the following modifications will need to be applied to Mobile Facility Configuration CL-02:

- Redesign of countertop configuration and frame assemblies.
- Removal of two cabinets.
- Addition of one ESD countertop to accommodate oxygen analyzer operation requirement.
- Removal of 28 VDC power supply and receptacles.
- Rearrangement of removable shelves.