



MF Program Action Item

Action Item Number: 5-62 Date Submitted: 04/30/10 Submitted By: MALS-14/ GySgt Gibson

Problem/Project Description:

200KW LOAD BANK, P/N LPH200D35584 AVTRON Publication.
Avtron publication does not provide sufficient troubleshooting procedures or parts labeling. The pub provides parts with part numbers, but does not give parts description or function. It also does not provide an Illustrated Parts Breakdown (IPB) to reference part location, only a wiring diagram.

Recommendation:

Recommend Avtron update the manual to provide better troubleshooting procedures, include a part description/function section, and incorporate an Illustrated Parts Breakdown (IPB) to reference part location. This should provide the technician a better understanding of Load Bank theory of operation and parts location to sufficiently troubleshoot and correct any problems.

Status/Course of Action: (Funded Yes No N/A)

07/15/11 - Accepted
05/03/11 – The manual and available source data needs to be reviewed to determine if an "in-house" effort is doable to make the changes requested. Action includes scope out the effort required and determination if current funding is sufficient to support this effort.
MFPO question – Do we not have this information in a publication in our inventory?

Action Agency: NAWCADLKE Assigned To: LCDR Davis Date Assigned: 05/03/10

Est. Completion Date: 06/30/12 Act. Completion Date: _____ Closed By: _____