

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 5-54

DATE SUBMITTED: 04/07/09

SUBMITTED BY: MALS-39

**PROBLEM:** The MF Checklist enclosure 1 to MCO13670.1 page 9 asks if double wide panels are stored out of the elements. Paragraph 6.3.5 refers back 19-25-177 which only explains how to place the MF side panel on top of a MF using a sling or crane or forklift. Furthermore AG-360MF-IIN-000 page 6-8 paragraph 6.2.9 states during the complexing process, side panel assemblies are secured on the roof of the associated MF side opening with bracket assemblies. This basically states store them on top using Z brackets and does not allow them to be stored out of the elements. If the side panel will be stored on top of a MF in the elements, it does not make sense to require them to be stored out of the elements.

**RECOMMENDATION:** Remove the requirement from the MCO inspection checklist.

**STATUS:** 5/1/09 Will be addressed during MCO revision. AI CLOSED.

**ACTION AGENCY:** ASL-34