

ACTION ITEM NO: 8-04

DATE SUBMITTED: 19 JUL 98

SUBMITTED BY: MALS-31

PROBLEM:

T-AVB Second Deck Ventilation

DISCUSSION:

While underway and in the operational mode, the Second Deck needs to be adequately ventilated to ease the build up of heat and overuse of the Environmental Control Units (ECU) within the Mobile Facilities (MF).

RECOMMENDATION:

Explore the possibility of adding more or larger exhaust fans to reduce the heat build up. While underway, the opening of Hold One Second Deck would allow a large increase in the amount of free-flowing air and thus extending the maintenance cycle of the ECU's.

STATUS: 29 JUL 98

Reject. The Logistics Review Group (LRG) Steering Committee held at JRB Ft. Worth, Texas on 29 Jul 98 request re-submit through Chain-of-Command to be forwarded to the next T-AVB Forum as lessons learned.