

ACTION ITEM NO: 2-149

DATE SUBMITTED: 28 JUL 98

SUBMITTED BY: MALS-16

PROBLEM:

NAVICP 00-35T-37-4 TBA increase for W/C 670 (MMF's)

DISCUSSION:

Lack of sufficient allowance in NAVICP 00-35T-37-4 Part III, section three for MMF configuration CL-01 (electrical/electronic calibration). W/C 670's current allowance for CL-01 is two (2). Due to recent DOD spending cuts and DEPOT level maintenance cut backs, Field Calibration Activities workload has been increased to absorb some of the Mobile Calibration Complex's and the Navy standards TYCOMS; therefore, 670's allowance for CL-01 MMF's requires adjustment from the current allowance of two to an allowance of four. The two additional MMF's will provide the necessary counter space for the additional calibration standards and bench space to perform safe maintenance on the additional workload.

STATUS: 29 JUL 98

Closed. COMMARFORPAC took for action during the Logistics Review Group (LRG) meeting held at JRB FT. Worth, Texas on 29 Jul 98 to validate the requirement.