



MF Program Action Item

Action Item Number: 1-128 **Date Submitted:** 04/21/10 **Submitted By:** MALS-14, W/C 620 (GySgt Randone)

Problem/Project Description:

Power fluctuations from the MF power source causes degradation of the sensitive electronic components of the Generator Control Unit Test Set (GCUTS). This degradation results in extended test set down time due to frequent component failure.

Recommendation:

Modify the Mobile Facility (Config GC-01) to facilitate the installation of line conditioners, P/N LC2400.

Status/Course of Action: (Funded Yes No N/A)

05/17/10 - Accepted

04/29/11 - The electrical modification drawing, MFGC010160, has been issued to install ceiling receptacles for the line conditioners. MFPO working with PMA to initiate final fix.

Action Agency: NI Engineering **Assigned To:** Lloyd Bjurman **Date Assigned:** 04/21/10

Est. Completion Date: 12/31/11 **Act. Completion Date:** _____ **Closed By:** _____