



MF Program Action Item

Action Item Number: 2011-124 Date Submitted: 06/28/11 Submitted By: MFPO/ MSgt Turner

Problem/Project Description:

ECU (R-134A) wire harness chaffing. Units have locally protected ECU harness with RTV, some are sleeved, some still subject to chaffing.

Recommendation:

Identify method of correcting problem of chaffing for all units, across the board.

Status/Course of Action: (Funded Yes No N/A)

Action Agency: NAWCADLKE - Eng Assigned To: _____ Date Assigned: _____

Est. Completion Date: _____ Act. Completion Date: _____ Closed By: _____