

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 3-79

DATE SUBMITTED: 21 August 2003

SUBMITTED BY: MALS-14, W/C 990 SNCOIC.

PROBLEM: Removing/Replacing MF Doors is entirely too time-consuming, especially when large numbers of MF's have to be Deployed and Complexed.

RECOMMENDATION: Install Quick-Connect/Disconnect Hinges on all MF's.

STATUS: 02 SEP 03

ACTION AGENCY:

NAWCADLKE CODE 4825

Open. NAWCADLKE Code 4825 to conduct research, findings to be provided.

COMPLETION DATE:

TBD

STATUS: 10 SEP 03

NEW ACTION AGENCY

NAWCADLKE 4827

REJECTED. NAWCADLKE CODE 4827 RECOMMENDED AT LOGISTICS REVIEW GROUP (LRG) MEETING HELD AT JACKSONVILLE, FLORIDA ON 10 SEP 03 THAT ACTION ITEM 3-79 TO BE REJECTED. THE HINGES ARE AN INTEGRAL PART OF THE SHELTER STRUCTURE AND ARE SIGNIFICANTLY LOADED IN RACKING. IF HINGE PINS WERE "ACCIDENTLY" REMOVED FROM SHELTER BEING TRANSPORTED VIA SHIP, THE SHELTER COULD FAIL RESULTING IN DAMAGE TO ITSELF AND OTHER CONTAINERS / SHELTERS. SIGNIFICANT COST WOULD BE INCURRED PERFORMING THE REQUIRED TESTING ON ALL THE SHELTER TYPES.