

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 3-87

DATE SUBMITTED: 04/20/07

SUBMITTED BY: SSgt Perales, W/C 69A, MALS-11

PROBLEM: ECU's are unreliable. ECU's tend to freeze up or outside fan motor does not work. After repair of the ECU's, they still do not blow cold air (usually its ambient air that they blow). Marines tend to put ECU in ON position instead of AUTO to keep the benches cool.

RECOMMENDATION: Replace ECU's with more reliable or durable units.

STATUS: 05/18/07 Closed. Repeat AI 3-86.

ACTION AGENCY: Mobile Facilities Program Office