

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 3-88

DATE SUBMITTED: 05/11/07

SUBMITTED BY: Sgt Gordon MARDET Keesler

PROBLEM: Small CSC discrepancies take too long to repair while deployed. Example: 990 sent an inspector out to our van and we needed to apply an anti corrosion compound to the rivets. Since the inspector didn't have any on him we had to wait and eventually embark it with out making the repair.

RECOMMENDATION: Make small modular kits with instructions for the various items inside. A "MF care guide".

STATUS: 05/18/07 Closed. This was a TD.

ACTION AGENCY: Mobile Facilities Program Office