

ACTION ITEM NO: 5-38

DATE SUBMITTED: 15 JUN 99

SUBMITTED BY: CG FIRST MAW

PROBLEM:

TECH PUB AG-180-MMM-000; Refrigerant Unit

DISCUSSION:

ST-1000 and/or suitable alternatives (if approved) are not listed in Tech Manual AG-180-MMM-000 as the designated S/E to perform recovery/recycle/recharge tasks associated with ECU maintenance. IMRL does list the ST-1000 as required S/E to support ECUs. Refer to S/E refrigerant chit # SE-001-99 for other concerns.

RECOMMENDATION:

Add required S/E (ST-1000), and/or alternatives to Tech Manual AG-180-MMM-000, WP7.

STATUS: 07 JUL 99

ACTION AGENCY:

TBD

COMPLETION DATE:

TBD

STATUS: 15 JUL 99

Closed. Refer to ACTION ITEM NO. 6-31 and ACTION ITEM NO. 6-32.