

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 6-45

DATE SUBMITTED: 04/18/08

SUBMITTED BY: SSgt Bollhoefer (MALS-31)

**PROBLEM:** There are no exhaust covers for the TQGs which allows moisture and debris to potentially intrude a generator in an unprotected environment and in a non-operational status.

**RECOMMENDATION:** Provide exhaust flap assy to prevent moisture and debris intrusion of the generator unit.

**STATUS:** 04/21/08 ACCEPTED--Input should have been suggested prior to contracting. Not warranted as all GSE with exhaust systems would require exhaust covers. Cost exceeds benefit/risk. Local manufacture as desired.

04/23/08 The open exhaust port on top of the TQG contains a pass through that will shed off all foreign material introduced through the top. Environmental intrusion such as sand and water are not an issue.

05/29/08 CLOSED--Manufacturer states no screen required as debris are passed to ground.

ACTION AGENCY: MF Program Office/NAWCADLKE