

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 7-46

DATE SUBMITTED: 20 MAY 2004

SUBMITTED BY: MALS-36, W/C 990

PROBLEM: Some series MF's, eg. RJF, have door openings that measure 6ft, 6in X 4ft, 1¾ in. Other MF's, eg. MWK, have door openings that measure 6ft, 5¾ in X 4ft, 2in. This creates a serious problem when installing a clip-style butting kit. It fits fine into the RJF, but to get it into the MWK takes four Marines pulling inwards from the center of each side until all four corners of the kit fit in place. This leaves gaps, specifically on the sides, which creates two one-inch openings to the outside. This is not a design flaw with the butting kit or any particular MF. It is simply a lack of attention to detail between two different MF manufacturers.

RECOMMENDATION: Manufacture, or create, our own butting kits to rectify the current situation. Pay special attention to all dimensions on future contracts, and ensure the design will marry up to older models.

STATUS: 01 JUN 04

ACTION AGENCY: TBD

STATUS: 17 JUN 04

Closed. In concurrence with discussions held by the Logistics Review Group (LRG) Open Forum in attendance at Atlanta, Georgia on 17 Jun 2004 it was determined that on a case-by-case basis all Fleet Personnel are to contact their respective NADEPNI / PWC Norfolk Configuration-Site UMSC Liaison so as to have furnished a proper-type/workable Butting-Kit.