

ACTION ITEM NO: 1-102

DATE SUBMITTED: 18 JUN 99

SUBMITTED BY: CG SECOND MAW

PROBLEM:

Environmental Control Units (ECU) Shoring Rods.

DISCUSSION:

As more and more different types of Mobile Facility (MF) are introduced, and the life extension of older (MF)'s are now beyond (20) twenty years, we now have a mixture of 3/8" rods and 1/4" rods. Inevitably, the rods through the years become lost, corroded or bent.

RECOMMENDATION:

By adding/modifying the (MF) to allow the use of channel steel bolted to the ceiling and floor, then attach the (ECU) by using self-locking nuts, will secure it for shipment. Once the (MF) is received, the receiving activity will remove the steel rods and secure them to the ceiling of the (MF) where they will stay until the (MF) is ready for transport. This will save manhours and cost. Pictures/Drawings can be provided upon request.

STATUS: 07 JUL 99

ACTION AGENCY:

TBD

COMPLETION DATE:

TBD

STATUS: 15 JUL 99

AGENCY:

NAWCADLKE (Code 3.1.4.4)

Open. NAWCADLKE Code 3.1.4.4 will investigate and provide findings.

COMPLETION DATE:

01 FEB 00