

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-114

DATE SUBMITTED: 27 MAR 06

SUBMITTED BY: MALS-24

PROBLEM: Circuit Breakers in MF Panels are not labeled. Outlets not numbered so as to easily identify which C/B controls it's power.

RECOMMENDATION: Have the MFG label C/B Pnls when MF is built. e.g. CB#1= Main, CB#2= Outlet #2 and so on and so forth.

STATUS: 21 JUN 06

ACTION AGENCY: NADEPNI (Code 48701)

Rejected. During FY-06 (MF) LRG, NADEPNI Code 48701 rejected Action Item 1-114 based on all (MF) Drawings are in compliance with National Electrical Code (NEC) Standards.