

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-115

DATE SUBMITTED: 29 MAR 06

SUBMITTED BY: MALS-24

PROBLEM: LAN/Telphone wiring running between and around MF's is unsightly and can be a trip hazard. Some of the newer INU's have connections for telephone lines but not LAN lines however none of the Admin type (CU01) MF's have telephone or LAN connections.

RECOMMENDATION: Hardwire MF's with internal and external jacks for telephone and LAN connections.

STATUS: 21 JUN 06

ACTION AGENCY: NADEPNI (Code 48701)

Rejected. During FY-06 (MF) LRG, NADEPNI Code 48701 rejected Action Item 1-115 based on constant design changes with industry-wide applications. Upon request, Fleet Users can be provided installation recommendations on a case-by-case basis.

