

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 1-119

DATE SUBMITTED: 04/16/07

SUBMITTED BY: MALS-24

**PROBLEM:** During heavy rain fall MF's will collect rain in upper seal of the doors. When opening the door the rain is dumped on personnel entering or exiting the MF.

**RECOMMENDATION:** Take a sheet of T-3 Aluminum and cut a piece 52" x 2 1/4 ". Then put a 45 degree bend in the aluminum to channel water away from door seal. The lip already provided on MF's door way is where you can insert the rain guard using a tube of 8802. This modification is in no way permanent and can be removed for shipment of the MF.

**STATUS:** 05/18/07 Closed. Manufactured locally.

**ACTION AGENCY:** Mobile Facilities Program Office