

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-121

DATE SUBMITTED: 04/21/08

SUBMITTED BY: MF Program Office

PROBLEM: Lithonia light fixtures are difficult to repair, due to part obsolescence issues. Also, the plastic light diffusers are extremely brittle and break easily when attempting to change fluorescent lights or repair electrical issues.

RECOMMENDATION: Replace all Lithonia light fixtures with Kenall light fixtures.

STATUS: 04/21/08 ACCEPTED--MF Program Office has initiated an effort to replace 100% of Lithonia light fixtures with Kenall lights at both MF Configuration Sites on all new builds and refurbishments. All Engineering Drawings will be updated to identify new light fixtures. All Lithonia lights will be replaced on an attrition basis. Will not be a Fleet SEC.

05/28/08 CLOSED--PO decision to replace all lighting doing attrition/rework.

ACTION AGENCY: NAWCADLKE