

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-123

DATE SUBMITTED: 04/01/09

SUBMITTED BY: MALS-31

PROBLEM: Clip on butting kits- 1. They are too big for many of the MF's. Dimensions for the butting kit are 50" wide X 77 3/4" tall, the doorway is 49" wide X 76 3/4" tall. The butting kits are rigid and not adjustable so they end up bowing in on the sides and top and don't seal correctly when they are forced into the door way of an older MF. 2. The thin foam seal that is glued on the butting kit. This seal usually gets ripped off when the butting kit is forced in to the doorway of a MF.

RECOMMENDATION: Make a new thumb screw style butting kit or one that is adjustable. For the seal they need to make one that is heavy duty rubber and is embedded into the butting kit, not just glued on.

STATUS: Accepted. 05/21/09 The initial investigation reveals that they are being produced by two separate manufacturers. We are requesting fleet input to determine which manufacturer is making them too large. 19 Jan 09 Fleet needs to provide QDRs. Program Office needs req#s from supply orders in order to do further research.

7/1/09 Previous action item dated [1985 \(#01-05\)](#) to change from Thumb screws to clips drove this requirement. Action Item Closed

ACTION AGENCY: NAWCADLKE