

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-124

DATE SUBMITTED: 05/18/09

SUBMITTED BY: MALS-14 SSgt Ermis

PROBLEM: Thermostats mounted to ECU faceplate causes the ECU to turn off before desired temperature is reached. Also, will keep ECU from cycling to keep optimum cooling regulated.

RECOMMENDATION: Move one closer to intake of RTCASS. Move second one across from auxilliary fan.

STATUS: Accepted. North Island engineering and Lakehurst Engineering will work on contract design changes with Gichner to move thermostats further from the front of the ECU. 05/21/09
Redirected to NI Engineering
7/1/09 NORIS Eng needs to respond.

ACTION AGENCY: NI Engineering