

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-128

DATE SUBMITTED: 04/21/2010

SUBMITTED BY: GySgt Randone, MALS-14 W/C 620 SNCOIC

PROBLEM: Power fluctuations from the MF power source causes degradation of the sensitive electronic components of the Generator Control Unit Test Set (GCUTS). This degradation results in extended test set down time due to frequent component failure.

RECOMMENDATION: Modify the Mobile Facility (Config GC-01) to facilitate the installation of line conditioners, P/N LC2400.

STATUS: Accepted

ACTION AGENCY: MF Engineering