

ACTION ITEM NO: 2-133

DATE SUBMITTED: 30 JUN 98

SUBMITTED BY: CG FIRST MAW MFC

PROBLEM:

No EN-01 rated on MALS-36 TBA.

DISCUSSION:

According to AMMRL, MALS-36 rates (2) Nitrogen/Oxygen generators, however, they are part of an MF Configuration EN-01. At this time MALS-36 rates no EN-01 as per the TBA.

SOLUTION:

TYCOMS need to get together and correct the TBA or AMMRL to coincide.

STATUS: 29 JUL 98

Closed. COMMARFORPAC took for action during the Logistics Review Group (LRG) meeting held at JRB Fort Worth, Texas on 29 Jul 98.