

ACTION ITEM NO: 2-139

DATE SUBMITTED: 19 JUL 98

SUBMITTED BY: MALS-31

PROBLEM:

FLIR POD Repair MF.

DISCUSSION:

Due to the expanding maintenance requirements and capabilities of the FLIR POD shop, a double-wide Mobile Facility (MF) hoists and maintenance benches is required to be added to the Table of Basic Allowance (TBA) and MF inventory.

RECOMMENDATION:

Although MALS-11 is currently evaluating the composite repair MF (CS-02A & 03B), these mobile facilities would require extensive modification and an addition of another hoist to facilitate the maintenance requirements of the FLIR POD shop.

The MF currently in the inventory that meets the FLIR POD requirements with very little modification (removal of the dip tank) is the ordnance MF's (GM-02A & GM-03B). MALS-31 has evaluated these mobile facilities and has determined that they meet or exceed all requirements. Request this item be added to the TBA to meet the ever increasing requirements of the FLIR POD maintenance concept.

STATUS: 29 JUL 98

Closed. The Logistics Review Group (LRG) Steering Committee held at JRB Ft. Worth, Texas on 29 Jul 98 request await the finalization of FLIR POD Shop establishment to accept proposed concept.