

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 2-183

DATE SUBMITTED: 03/27/07

SUBMITTED BY: Sgt Neal, MALS-41

PROBLEM: Work Center 640 needs a double wide MF for there POD maintenance. Even when they had a work load of 7 FLIR POD's the one single wide was too small, now the work load has been increased to 17 FLIR POD's and are expected to also start supporting ATFLIR POD's. This increase is due to the change in responsibilities, we went from supporting this base to supporting FRC WEST.

RECOMMENDATION: Create a Facility that has the required specs. to support the mission of 640 and FRC WEST. They need 400HZ and at least two over head cranes in each double wide set. They would also like it to have the same configuration as the CS-02A, which is 500 divisions composite repair shop.

STATUS: 05/18/07 Assumed by ASL-34.
03/24/09 - Item Closed due to sun-down of equipment.

ACTION AGENCY: ASL, Simpson, MGySgt, Headquarters Marine Corps 703-693-9796.