



MF Program Action Item

Action Item Number: 2011-128 Date Submitted: 06/29/11 Submitted By: MASL-14/ CWO-5 LeBlanc

Problem/Project Description:

SOMF Panel bolts strip all the time resulting in bolt heads being cut off/drilled out. Panels that have been off for an extended time are difficult to reinstall due to fastener problems. Panels end up being secured via tie-down straps creating a safety issue.

Recommendation:

Research feasibility of using bolts that go completely through and are fastened with a nut on the inside of the MF.

Status/Course of Action: (Funded Yes No N/A)

Action Agency: NAWCADLKE Assigned To: _____ Date Assigned: _____

Est. Completion Date: _____ Act. Completion Date: _____ Closed By: _____