



MF Program Action Item

Action Item Number: 2011-129 Date Submitted: 06/29/11 Submitted By: MALS-31

Problem/Project Description:

Receiving wrong fan belt for TQG

Recommendation:

There are two styles of belts for the TQG, a slotted type and solid type. Supply should not substitute the slotted belt for the solid belt. The correct belt is from CAT.

Status/Course of Action: (Funded Yes No N/A)

Action Agency: NAWCADLKE Assigned To: _____ Date Assigned: _____

Est. Completion Date: _____ Act. Completion Date: _____ Closed By: _____