

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 3-83

DATE SUBMITTED: 04/16/07

SUBMITTED BY: MALS-24

PROBLEM: Circuit Breaker monitoring panel involves multiple steps in order to trouble shoot circuit breakers resulting in an unsafe and timely evolution for technicians.

RECOMMENDATION: Use power distribution panel similar to config. VD-08B where the whole assembly is hinged open, not just the access door. Attach circuit breaker panel board to the back side of access door allowing circuit breakers to swing out with panel allowing for access to back side of circuit breakers. This will minimize the prep time and troubleshooting time for distribution panels.

ACTION AGENCY: North Island Engineering

STATUS: 05/18/07 Under Review.

06/18/07 - Recommendations provided by North Island Engineering. After discussion, MF Program Office will make final decision which option to follow during the IPT.

03/01/08 - Recommendations are not Cost Effective to implement. Action Item Closed.