

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 3-93

DATE SUBMITTED: 04/13/09

SUBMITTED BY: COMMARFORPAC ALD-E

**PROBLEM:** Convention for Safe Container recertification for EA-01 and EA-02 MFs cannot be accomplished IAW the MIL-HDBK-138B. MIL-HDBK-138B para 5.1.2 states "A container must bear legible ISO markings to conform to ISO Standard 6346". EA-01 and EA-02 MFs are not assigned ISO numbers and CSC inspectors cannot legitimately recertify them as CSC compliant.

**RECOMMENDATION:** Add ISO numbers to EA-01 and EA-02 MFs or remove CSC Safety Approval Plate..

**STATUS:** Accepted. This configuration will be sundowned and replaced by humvee mounted assets. There have been modifications to this configuration that have not been certified CSC compliant. Direction to remove CSC data plates will follow.  
05/21/09 Naval message from Program Office to remove CSC requirement in draft. AI CLOSED.

ACTION AGENCY: MF Program Office