

**MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM**

ACTION ITEM NO.: 5-59

DATE SUBMITTED: 4/13/2010

SUBMITTED BY: MALS-39

PROBLEM: The configurations on the MF website do not always match what is in the Configuration Manual AG-360MF-CCD-000. Not only that, but the website doesn't include the listing of what the gear in each configuration is. A good example of configurations that do not match between the website and the config manual is the CU-01.

RECOMMENDATION:

The configuration manual was just recently updated. Find out which drawings are correct and update either the config manual or the website as needed. As for the website, include with all of the drawings, a listing of what the gear is. A good example of this can be found in the configuration manual.

STATUS: Accepted

ACTION AGENCY: MF Program