

ACTION ITEM NO: 7-38

DATE SUBMITTED: 19 JUL 98

SUBMITTED BY: MALS-31

PROBLEM:

Two-Bulb Light-Diffuser Assembly.

DISCUSSION:

The Fleet has attempted to order Two-Bulb Light-Diffusers and the system is not stocked with the items. After careful review of the Allowance Parts List (APL) the Light-Diffusers were never provisioned for the Mobile Facilities (MF).

RECOMMENDATION:

It is requested that NAWCAD Lakehurst identify and provision the requirement to NAVICP Mechanicsburg to allow procurement of Two-Bulb Light-Diffusers to meet Fleet demands.

**STATUS: 29 JUL 98**

ACTION AGENCY:

NAWCADLKE (Code 4825)

Open. NAWCADLKE Code 4825 to provide analysis.

COMPLETION DATE:

16 NOV 98

**STATUS: 02 DEC 98**

Closed. Per NAVICP-M, it is not cost effective to set-up just the diffuser in the supply system. He recommends ordering the whole light-assembly, which includes the diffuser.