

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 7-47

DATE SUBMITTED: 07 JUN 04

SUBMITTED BY: **MALS-24 AVIONICS CHIEF**

Unable to create proper environmental seal with environmental curtain part number (65006V) when mated to butting kit part number (1339AS471-1). The environmental curtain must be properly installed in the Calibration Lab (W/C 670) in order to maintain the strict temperature and humidity standards required by NA17-35FR-06. When these critical temperature and humidity parameters are not met, calibration cannot be performed and mission support capabilities are lost.

RECOMMENDATION:

1. Modify environmental curtain part number (65006V) to facilitate proper installation with butting kit part number (1339AS471-1).
2. Manufacture new environmental curtain to properly mount with butting kit part number (1339AS471-1).

STATUS: 09 JUN 04

ACTION AGENCY: TBD

STATUS: 17 JUN 04

Closed. NAVAIR CODE 3.2.4.10 during an Open Forum Discussion at the Logistics Review Group (LRG) held at Atlanta, Georgia on 17 Jun 2004 requested that respective Fleet-Sites submit via Naval Message to the (MF) Program Office an (MF) Configuration-Modification Request to be incorporated into specific MF SER NO and CONFIG CODE being affected.