



DEPARTMENT OF THE NAVY

NAVAL AIR WARFARE CENTER AIRCRAFT DIVISION

IN REPLY REFER TO:

13052

Ser 4.8.10.7B596-1/0367

02 FEB 1996

From: Head, Airframe/Servicing Support Equipment Branch, Support Equipment And Aircraft Launch And Recovery Equipment Inservice Engineering Division (Code 4.8.10.7B596-1), Naval Air Warfare Center Aircraft Division, Highway 547, Lakehurst, NJ 08733-5090

Subj: SUPPORT EQUIPMENT BULLETIN NO. 708, TD CODE 63, MOBILE FACILITY, AIR CONDITIONER PANEL

Ref: (a) Mobile Facility Action Review Meeting

Encl: (1) Air Conditioning Panel Diagram

1. COG Code: NAVAIRWARCENACDIV Lakehurst, code 4.8.10.7, T. Zalepa, DSN 624-1953, COMM (908) 323-1953.

2. CATEGORY: Routine

3. DOCUMENTATION AFFECTED:

a. DWG NO	TITLE	REV	CAGE
1339AS775	PANEL, AIR CONDITIONER MOBILE FACILITY	D	30003

b. NAVAIR 19-25-177, technical manual, operation and intermediate maintenance with illustrated parts breakdown, mobile facilities of 01 May 1990.

4. PURPOSE: To inform users of the Environmental Control Units (ECU) to connect the compressor to the power source for a minimum of four hours prior to ECU operation.

5. APPLICATION:

13052

Ser 4.8.10.7B596-1/0367

02 FEB 1996

Subj: SUPPORT EQUIPMENT BULLETIN NO. 708, TD CODE 63, MOBILE FACILITY, AIR CONDITIONER PANEL

a. Basic Equipment:

NOMENCLATURE	SERIAL NO.	QUANTITY
Mobile Facility	All	4700

b. Trainers: N/A

c. Spares: N/A

6. COMPLIANCE:

a. Basic Equipment: Inspection and repair shall be performed at the organizational/intermediate maintenance activities no later than 60 days after bulletin issue.

b. Trainers: N/A

c. Spares: N/A

7. MAN HOURS:

a. Basic Equipment:

NO. OF MEN	SKILL	TOTAL M/H
1	AS (NAVY) / 6XXX (MARINE CORP)	0.5

b. Trainers: N/A

c. Spares: N/A

8. SUPPLY DATA:

a. Basic Equipment:

13052

Ser 4.8.10.7B596-1/0367

0 2 FEB 1996

Subj: SUPPORT EQUIPMENT BULLETIN NO. 708, TD CODE 63, MOBILE FACILITY, AIR CONDITIONER PANEL

(1) Parts/material required

QTY	PART NO.	NOMENCLATURE	SM&R	NSN	SOURCE
AR	1339AS485-1	DECAL	TBD	TBD	(A)

(2) Peculiar support equipment required: N/A

(3) Parts/material removed: N/A

(4) Source of supply: Requisition decals via Naval message from NAVAVNDEPOT North Island CA, code 023A or PWC Norfolk VA, code 30M depending on what coast user is located on.

b. Trainers: N/A

c. Spares: N/A

9. REIDENTIFICATION: N/A

10. DETAILED INSTRUCTIONS:

a. Locate the air conditioner panel on the side of the mobile facility. Make sure there is no dirt, dust, grease, oils or any other foreign material on the surface of the panel assembly (see fig. 1). Make sure the paint is in good condition, not flaking or peeling, so that the decal has proper adherence.

b. Peel the back of the decal to expose the adhesive. Be sure that the decal is not up-side-down. Place the decal on the plenum assembly panel with the decal's lower left corner 12 inches down from the top left corner of the plenum assembly panel, and 6.6 inches to the right of the plenum assembly panel's left edge (see figure 1 for an illustration). This should place

13052

Ser 4.8.10.7B596-1/0367

0 2 FEB 1996

Subj: SUPPORT EQUIPMENT BULLETIN NO. 708, TD CODE 63, MOBILE FACILITY, AIR CONDITIONER PANEL

the decal at the center of the available space on the plenum assembly panel, if this is not the case adjust accordingly.

11. WEIGHT AND BALANCE: N/A

12. RECORDS AFFECTED:

a. Enter compliance Support Equipment custody and maintenance record (OPNAV 4790.60).

b. Report compliance through VIDS/MAF from (OPNAV 4790/60) and technical directive status accounting system.

13. VERIFIED BY: Waived per NAVAIRSYSCOM, AIR-4152A9

14. RECISSION DATE: 30 June 1997

15. RELATED INSTRUCTIONS: TYCOMS to provide widest possible dissemination.



J. E. KRAUS

Distribution:

COMNAVAIRLANT (N422B23)

COMNAVAIPAC (N422B)

COMNAVAIRESFOR (Code 574)

COMMARFORLANT

CNATRA (PMA-251)

CG 1ST MAW


CG 2ND MAW

CG 3RD MAW

CG 4TH MAW

Copy to:

COMNAVAIRSYSCOM (AIR-3.6.4.1)



PANEL, AIR CONDITIONER

FIG 1