


Naval Air Systems Command Mobile Facility Program

TW-05A/TW-06B Redesign Survey

TW-05A/TW-06B Proposed Redesign Survey



TW-05A/TW-06B Redesign Purpose

- PMA-260 procurement of new parts washers
 - Sink Aqueous Part Washer (SAPW)
 - NIIN: 01-570-3858
 - Aqueous Solvents Parts Washer (ASPW)
 - NIIN: 01-572-9921
- New parts washers require a redesign/reconfigure of current TW-05A/TW-06B Mobile Facilities




TW-05A/TW-06B Redesign Questions

- When reviewing the proposed drawings, questions to ask/answer are:
 - Is there enough available space to safely operate?
 - Should the MF be a Triple Wide configuration?
 - Are the cabinets still required or can the tool cabinet and Ultra-low Temp cabinet be eliminated resulting in more floor space?
 - Do you need an air compressor/air supply source?
 - What is currently being used today to supply air?
 - Are all four of the sinks required against the bulk head?
 - If not, which sink(s) should we remove?
 - Is the IMRL equipment still valid, i.e. Press, Bead breaker, etc?
 - Do you have it on hand?
 - Is it installed in the MF still?
 - What is the material readiness condition of these items?



Top View Down rough layout


TW-05A/TW-06B Redesign Survey






Ceiling view of lights layout

TW-05A/TW-06B Redesign Survey




Top View Down 3-D layout

TW-05A/TW-06B Redesign Survey




TW-05A side 3-D layout

TW-05A/TW-06B Redesign Survey




TW-06B side 3-D layout





TW-05A/TW-06B 3-D layout

TW-05A/TW-06B Redesign Survey





TW-05A/TW-06B 3-D layout

TW-05A/TW-06B Redesign Survey

