

MOBILE FACILITY PROGRAM REVIEW  
ACTION ITEM

ACTION ITEM NO.: 4-17

DATE SUBMITTED: 04/25/07

SUBMITTED BY: GySgt Houchins, W/C 990 MALS-11

PROBLEM: Support equipment Marines and Sailors assigned to work center 990 are trained in the theory of operation of an air conditioning unit, however they are not school trained to repair an A/E32C-45, environmental control unit (ECU).

RECOMMENDATION: Add troubleshooting and maintenance of the A/E32C-45 (ECU) to the 6073 MOS training track.

STATUS: 05/18/07 Closed. GSE HPPR Chit Required.

ACTION AGENCY: N/A