

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 1-120

DATE SUBMITTED: 04/21/08

SUBMITTED BY: MF Program Office

PROBLEM: MF Program Office would like to replace Lonseal with non-skid, Line-X, Toff Liner or Rhino Lining. Lonseal tears, stains, is extremely slick, and difficult to remove and replace at MF Configuration Sites.

RECOMMENDATION: Determine suitable replacement for Lonseal.

STATUS: 04/21/08 ACCEPTED--MF Program Office installed non-skid in PMA-213 MFs. Would like replacement floor covering to be added into future Gichner MF shell purchases (contract). NAWCAD Lakehurst and Gichner exploring alternate solutions. Need Fleet requirement. 05/28/08 Further research into Rhino Liner vice non-skid presented at LRG. 01/29/09 Program working this issue within the IPT. LKE researching several options. 05/21/09 The Program Office needs input from the fleet regarding the type of flooring desired. 7/1/09 NEED LKE INPUT

ACTION AGENCY: NAWCADLKE