

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 2-173

DATE SUBMITTED: 21 MAY 04

SUBMITTED BY: MALS-12, W/C 990, TBA REQUIREMENT

The F18 community has been operating with the Pod Shop concept for at least the last 15 years. It is the accepted method of maintaining the AN/AAS-38 FLIR Pod and AN/ASQ-173 LDT Pod. They need a double wide deployable MF to work on these systems properly. During a recent survey visit, MF Program V.I.P.'s and I discussed having a double wide designated for the Pod Shop.

RECOMMENDATION: Re-designate GM-03B and GM-02A double wide gun MF's as Pod Shop MF's and distribute to each MALS supporting FA-18s.

STATUS: 01 JUN 04

ACTION AGENCY: TBD; SEE RELATED ACTION ITEM NO. 2-139

STATUS: 17 JUN 04

Closed. In concurrence with discussions held by the Logistics Review Group (LRG) Open Forum in attendance at Atlanta, Georgia on 17 Jun 2004, NAVAIR Code 3.2.4.10 requests that MALS-12 provide further written-requirements clarification and to re-submit TBA Requirement to HQMC ASL-34 via proper WING/TYCOMS Chain-of-Command.