



MF Program Action Item

Action Item Number: 2011-101 Date Submitted: 03/21/11 Submitted By: MALS-24 / Cpl Matthew Costello

Problem/Project Description:

There is a lack of storage for the ECU shoring kits and Mobile facility shipping parts (ie. D-rings, Straps). Parts laid out can be considered FOD hazards in Maintenance Facilities.

Recommendation:

Have an internal compartment designed into the configuration of each mobile facility to ensure proper accountability and storage are provide to the O-Level user. This will also help keep assets from being considered a FOD hazard.

Status/Course of Action: (Funded Yes No N/A)

Small Unit Leadership! Locally develop a plan to manage inventory equipment.

Action Agency: MFPO Assigned To: MSgt Turner Date Assigned: 05/03/11

Est. Completion Date: 05/31/11 Act. Completion Date: 05/17/11 Closed By: MSgt Turner