



MF Program Action Item

Action Item Number: 2011-113 **Date Submitted:** 03/21/11 **Submitted By:** MALS-24/ Cpl Matt Costello

Problem/Project Description:

Multiple mobile facilities are missing major related equipment from mobile facility configuration.

Recommendation:

Add a step into the 364 day inspection in MRC deck (NA19-600-152-6-2), requiring a joint inventory inspection of configuration to ensure major related equipment is being accounted for by work center supervisors and MFC.

Status/Course of Action: (Funded Yes No N/A)

04/28/11 - MARFORPAC comments: Do not concur. Unit MFC is already empowered to accomplish this.

05/23/11 - MARFORCOM comments: It should be up to the individual work centers (users) to validate their own requirements. W/C 990 can use the LIRS and config manual to verify what IMRL/major related equip is present or missing in the MF.

06/06/11 - Maintaining MF configuration integrity is the responsibility of the local MALS leadership. Each MF LIR contains applicable equipment inventory as constant WC Supervisor/ MFC reference. This office does not deem necessary the development of a recurring inspection requirement. Concur, no update to 364 Day.

Action Agency: MFPO **Assigned To:** MSgt Turner **Date Assigned:** 05/03/11

Est. Completion Date: 05/31/11 **Act. Completion Date:** 06/15/11 **Closed By:** MSgt Turner