

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 6-42

DATE SUBMITTED: 06/27/07

SUBMITTED BY: MALS-16

PROBLEM: Mobility of 100/200 TQGs. The TQGs can only be moved by a forklift, requiring the MALS to use the local MWSS forklift and operator. Currently, in theatre, it would require coordinating a forklift, a forklift operator, or 5 or 7 ton truck and operator, two W/C 990 personnel to all be available at the same time to move an RFI asset from the MALS pool to the site where the NRFI asset is and return with the NRFI asset.

RECOMMENDATION: Supply the TQGs with running gear. Then this same evolution could occur with just the two C/C 990 Marines using a tow tractor or HUMVEE.

STATUS: 04/30/08 CLOSED--When FY04/05 Program funding was allocated for the TQG purchases the decision was made that the running gear would not be used. Lack of POM planning and prior inputs negate the ability to purchase running gear.

05/29/08 CLOSED--No action required.

ACTION AGENCY: NAWCADLKE