

ACTION ITEM NO: 7-40

DATE SUBMITTED: 18 JUN 99

SUBMITTED BY: CG SECOND MAW

PROBLEM:

Accustats

DISCUSSION:

Currently, all Accustats are considered Field-Level Repairable 3H Cog, cost \$108.00, with a SM&R Code of "PAGZZ", in laments terms worked on and disposed by the IMA. For the 990 to order a new Accustat, we first must cut a Level I MAF against the Mobile Facility (MF), second, remove and replace the repairable item, add N249, create Turn-In Level II MAF. Bubble-wrap the old Accustat, send to AMSU, along with Level II MAF, then induct Accustat to 990 for repair. Once received by 990 for repair, the Work Center will BCM 9 the item (condemned throw-away at the I-Level). Now the Accustat is on order. Once the new Accustat is received, 990 installs item and completes the MAF. Enormous Manhours are expended for an item that only cost \$108.00, which eventually will be thrown away. You can individually order each piece of the Accustat separately, and it is then considered Consumable.

RECOMMENDATION:

Make the item a Consumable, 9G Cog.

STATUS: 07 JUL 99

ACTION AGENCY:

TBD

COMPLETION DATE:

TBD

15 JUL 99

NEW ACTION AGENCY:

NAWCADLKE (Code 3.1.4.4)

Open. NAWCADLKE Code 3.1.4.4 will investigate and provide findings.

COMPLETION DATE:

01 OCT 99

STATUS: 13 JAN 00

Open. On-going investigation by NAWCADLKE Code 3.1.4.4 to provide findings.

COMPLETION DATE:

15 MAR 00

STATUS: 05 MAY 00

Closed. Reference NAVAIRWARCENACDIV LAKEHURST NJ Code 3144 MSG DTG 280833Z MAR 00.