

MOBILE FACILITY PROGRAM REVIEW
ACTION ITEM

ACTION ITEM NO.: 7-45

DATE SUBMITTED: 27 MARCH 02

SUBMITTED BY: MALS -24- SSGT Shanks, J.W.
DSN 257-0082/2242

PROBLEM: : Although the new "clip" style butting kit is more durable and built better than it's predecessor, it doesn't fit MFs configured before the SUE series. The new butting kits are approximately 1 1/2" larger than the door openings on MFs in these series. They also require inevitable modification to allow for fiber optic cables and phone lines.

RECOMMENDATION: : To allow for the size gap, an adapter butting kit should have one side fit to the new style MFs and the other side made smaller to fit all older MFs. This will be required due to the fact that inter-complexing between the different series is unavoidable as well as practical. They should also incorporate a sealable port located on the bottom to permit LAN lines to enter.

STATUS: 06 JUN 02

ACTION AGENCY:

NAWCADLKE CODE 4825

Open. NAWCADLKE Code 4825 to provide findings.

COMPLETION DATE:

TBD

STATUS: 13 FEB 03

Closed. There is no dimensional change between new clip style Butting-Kits and older Butting-Kits. Any misfit is due to some discrepancy in materials. When these discrepancies are found they should be reported through the appropriate reporting system, ROD, EI/HMR, TPDR. A flap has been incorporated into the Butting-Kits to allow pass-thru of cables, Butting Kits with this flap should be arriving at Configuration Sites in January 2003.