

RTTUZYUW RHOIAAA0001 3301522-UUUU--RHSSUU.

ZNR UUUUU

R 250126Z NOV 19 MID510000736178U

FM COMNAVAIRFOR SAN DIEGO CA

TO AIG 428

INFO COMNAVAIRLANT NORFOLK VA

COMNAVAIRPAC SAN DIEGO CA

BT

UNCLAS

MSGID/GENADMIN/MIL-STD-6040(SERIES)/B.0.01.00

/COMNAVAIRFOR SAN DIEGO CA/-/20191120Z//

SUBJ/NAVAL AVIATION MAINTENANCE PROGRAM INTERIM CHANGE 5//

REF/A/MSGID:DOC/COMNAVAIRFORINST 4790.2C/-/YMD:20170115//

AMPN/REF A is the Naval Aviation Maintenance Program (NAMP).//

PPOC/W.T. Ainsworth/CIV/COMNAVAIRFOR NAMP Manager/N422C/

SAN DIEGO CA/TEL:(619)545-1469/EMAIL:will.ainsworth@navy.mil//

GENTEXT/REMARKS/1. COMNAVAIRFORINST 4790.2C Interim Change 5 has been released and is effective immediately.

2. Interim Change 5 affects Depot procedures in various Chapter 10 NAMPSOPs, and is only applicable to Fleet Readiness Centers East, Mid-Atlantic, Northwest, Southeast, Southwest, West and Westpac Depot maintenance activities. Interim Change 5 does not apply to any Navy or Marine Corps O-level or I-level activity.

3. A copy of Interim Change 5 has been posted on the NAVAIR SharePoint website (<https://myteam.navair.navy.mil/KM/60/business-processes/air-6-7/NAMP>). If you need assistance in accessing NAVAIR SharePoint, contact ASCS Hicks, DSN: 757-9065, COMM: 301-757-9065, email: mark.a.hicks4@navy.mil.

4. Depot FRCs will direct questions regarding Interim Change 5 procedures to Mr. Doug Gray, COMFRC Safety and Compliance, tel: (301) 342-4482, email: douglas.gray@navy.mil.//

BT

#0001

NNNN